



Photo#1: There is no evidence of the AL Well on this Active Location.

December 27, 2016

Inspection Photos: Encana AL KRK 8-12C API#045-11569



Photo#2: There is no evidence of the AL Well on this Active Location. View over GPS Position at edge of Pad area

December 27, 2016

Inspection Photos: Encana AL KRK 8-12C API#045-11569