

# Reclamation Inspection

12/29/2016

Operator: Noble

Location ID: 327002

Weld County, CO

SESE Section 34 T9N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 2:** Photo taken south of the location, where the access road intersects County Road 98, facing east. Photo shows reclamation in process.



**Figure 3:** Photo taken from the access road, south of the location, facing east. Photo shows straw wattles used as a stormwater and sediment control BMP.



**Figure 4:** Photo taken from the southeast corner of the location, facing west. Photo shows reclamation in process.



**Figure 5:** Photo taken from the southeast corner of the location, facing northwest. Photo shows reclamation in process.



**Figure 6:** Photo taken from the southeast corner of the location, facing north. Photo shows reclamation in process.



**Figure 7:** Photo taken from the south end of the location, facing west. Photo shows pipe riser equipment and trash (barrel) remain on location. Insp. Doc. # 682500503 required operator to remove this equipment and trash.



**Figure 8:** Photo taken from the southeast corner of the location, facing southeast. Photo shows reclamation in process along access road.