

Chevron
Fee 73X flowline
release and remediation
photos

Release point



Cave in



Spill path at release point



Siphon 43 Dewatering



Release point cleaned



Upper spill path dug out



Spill path water washing



Siphon 43 remediated

