

Final Reclamation Inspection



Photo 1. Photo taken of well sign for API #123-26489 confirming well release of API #123-07653 on an active location.

Final Reclamation Inspection



Photo 2. Photo taken from location, facing North, confirming only one (1) PR well at Location ID 336322.