

# Final Reclamation Inspection



**Photo 1.** Photo taken of well sign for API #123-20009 confirming well release of API #123-17541 on an active location ; therefore, this is a well release on an active location.

# Final Reclamation Inspection



**Photo 2.** Photo taken of well sign for API #123-33698 confirming well release of API #123-17541 on an active location; therefore, this is a well release on an active location.