

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2016

Submitted Date:

12/25/2016

Document Number:

673714590

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
417917 \_\_\_\_\_ Sherman, Susan \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96340  
 Name of Operator: WIEPKING-FULLERTON ENERGY LLC  
 Address: 4600 S DOWNING ST  
 City: ENGLEWOOD State: CO Zip: 80113

**Findings:**

- 14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone          | Email                    | Comment                         |
|--------------|----------------|--------------------------|---------------------------------|
| Halde, Kerry | (719) 340-0329 | haldesand@centurytel.net | <a href="#">All Inspections</a> |
| Herian, Tim  | (316) 655-9200 | therian1@cox.net         | <a href="#">All Inspections</a> |
| Boone, Linda | (720) 271-8605 | LDBoonePar@aol.com       | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 417923      | WELL | PR     | 05/28/2011  | OW         | 073-06422 | BUBBA-STATE 2 | PR          |

**General Comment:**

**Location**

Overall Good:

| <b>Signs/Marker:</b> |                      |       |  |
|----------------------|----------------------|-------|--|
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

| <b>Fencing/:</b>   |              |       |  |
|--------------------|--------------|-------|--|
| Type               | PUMP JACK    |       |  |
| Comment:           | steel panels |       |  |
| Corrective Action: |              | Date: |  |
| Type               | LOCATION     |       |  |
| Comment:           | barbed wire  |       |  |
| Corrective Action: |              | Date: |  |

| <b>Equipment:</b>             |                                  |       | corrective date |
|-------------------------------|----------------------------------|-------|-----------------|
| Type: Emission Control Device | # 1                              |       |                 |
| Comment:                      | concrete pad                     |       |                 |
| Corrective Action:            |                                  | Date: |                 |
| Type: Ancillary equipment     | # 2                              |       |                 |
| Comment:                      | gas scrubber, chemical container |       |                 |
| Corrective Action:            |                                  | Date: |                 |
| Type: Deadman # & Marked      | # 4                              |       |                 |

|                               |  |       |  |
|-------------------------------|--|-------|--|
| Comment:                      |  | Date: |  |
| Corrective Action:            |  | Date: |  |
| Type: Pump Jack               | # 1  |       |  |
| Comment:                      |  | Date: |  |
| Corrective Action:            |  | Date: |  |
| Type: Vertical Heater Treater | # 2  |       |  |
| Comment:                      | shed, 2 concrete pads, earth berms, GPS 39.16607, -103.58292 | Date: |  |
| Corrective Action:            |  | Date: |  |
| Type: Prime Mover             | # 1  |       |  |
| Comment:                      | gas engine   | Date: |  |
| Corrective Action:            |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | 300 BBLs | STEEL AST |         | 39.165710,-103.582790 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 2 | 300 BBLs | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   |          |                |         | Date:  |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

| Type               | Capacity                      | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-------------------------------|---------------------|---------------------|-------------|
|                    |                               |                     |                     |             |
| Comment:           | same berms as crude oil tanks |                     |                     |             |
| Corrective Action: |                               |                     |                     | Date:       |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Venting:</b>    |  |       |  |
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Location Construction**

Location ID: 417923 CDP: \_\_\_\_\_

Comment:

Corrective Action:  **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:  **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:  **Date:** \_\_\_\_\_

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:  
 Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:  
 Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_  
 Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:  
 Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 417923 Type: WELL API Number: 073-06422 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. Oct 2016 reported to COGCC database.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: pasture, interim reclamation good

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     |         |
| Gravel           | Pass            | Gravel                  | Pass                  |  |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description            | URL   |
|--------------|------------------------|---|
| 673714590    | INSPECTION SUBMITTED   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037341">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037341</a> |
| 673714600    | Wiepking Bubba-State 2 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037333">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4037333</a> |