

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/28/2016

Submitted Date:

12/28/2016

Document Number:

674004725**FIELD INSPECTION FORM**
 Loc ID 336167 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292037	WELL	PR	04/07/2010	OW	123-26216	DOUTHIT 10-26	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal Picket		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared with API 05-123-26215				
Corrective Action:				Date:	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			
Corrective Action:			Date:	

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 292037 Type: WELL API Number: 123-26216 Status: PR Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
MIT Test. Held constant pressure at 380 PSI for 15 minute interval.	carlilec	12/28/2016

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674004725	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4038800">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4038800</a>