

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2016

Submitted Date:

01/03/2017

Document Number:

666802829**FIELD INSPECTION FORM**

Loc ID 335264 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211289	WELL	PR	04/22/1996	GW	045-07048	GIBSON GULCH UNIT 6-30	SI
262319	WELL	PR	11/02/2002	GW	045-08014	GIBSON GULCH UNIT 7-30	PR
262320	WELL	PR	08/06/2002	GW	045-08015	GIBSON GULCH UNIT 5-30	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 3

Comment: Corrective Action: Date: 

Type: Horizontal Heated Separator

# 3

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 3

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	<100 BBLS	PBV STEEL		,	
Comment: Centralized battery						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
CONDENSATE		2	300 BBLS	STEEL AST				39.499478,-107.598616		
Comment:										

Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	YES					
Comment:	Bradenhead valves open					
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**Facility ID: 211289 Type: WELL API Number: 045-07048 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Last production numbers posted Oct 2016

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 262319 Type: WELL API Number: 045-08014 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 262320 Type: WELL API Number: 045-08015 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Ditches	Pass			
Berms	Pass					
		Culverts	Pass			
Ditches	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT