

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2016

Submitted Date:

01/03/2017

Document Number:

666802834**FIELD INSPECTION FORM**

Loc ID 335281	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 15 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																							
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>VANGUARD OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>																																																																																											
Contact Information: <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Ghan, Scott</td> <td></td> <td>sghan@vnrlc.com</td> <td>Sr. EH&S</td> </tr> <tr> <td>Axelson, Aaron</td> <td>970-230-0926</td> <td>aaxelson@vnrlc.com</td> <td>Sr. Production Foreman</td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Ghan, Scott		sghan@vnrlc.com	Sr. EH&S	Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman																																																																											
Contact Name	Phone	Email	Comment																																																																																								
Ghan, Scott		sghan@vnrlc.com	Sr. EH&S																																																																																								
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	Sr. Production Foreman																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>211391</td><td>WELL</td><td>PR</td><td>08/08/2000</td><td>GW</td><td>045-07151</td><td>GIBSON GULCH UNIT 1-30</td><td>PR</td></tr> <tr><td>263754</td><td>WELL</td><td>PR</td><td>03/01/2011</td><td>GW</td><td>045-08137</td><td>GIBSON GULCH UNIT 2-30</td><td>PR</td></tr> <tr><td>284608</td><td>WELL</td><td>PR</td><td>05/10/2007</td><td>GW</td><td>045-12218</td><td>GGU DALEY 41B-30-691</td><td>PR</td></tr> <tr><td>284609</td><td>WELL</td><td>PR</td><td>05/12/2007</td><td>GW</td><td>045-12217</td><td>GGU DALEY 44A-19-691</td><td>PR</td></tr> <tr><td>300468</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17905</td><td>GGU DALEY 11A-29-691</td><td>PR</td></tr> <tr><td>300469</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17906</td><td>GGU DALEY 12C-29-691</td><td>PR</td></tr> <tr><td>300470</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17907</td><td>GGU DALEY 11D-29-691</td><td>PR</td></tr> <tr><td>300471</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17908</td><td>GGU DALEY 41A-30-691</td><td>PR</td></tr> <tr><td>300472</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17909</td><td>GGU DALEY 44B-19-691</td><td>PR</td></tr> <tr><td>300473</td><td>WELL</td><td>PR</td><td>02/16/2010</td><td>GW</td><td>045-17910</td><td>GGU DALEY 41C-30-691</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR	263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR	284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR	284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR	300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR	300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR	300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR	300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR	300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR	300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																				
211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR																																																																																				
263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR																																																																																				
284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR																																																																																				
284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR																																																																																				
300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR																																																																																				
300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR																																																																																				
300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR																																																																																				
300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR																																																																																				
300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR																																																																																				
300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR																																																																																				

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211391	WELL	PR	08/08/2000	GW	045-07151	GIBSON GULCH UNIT 1-30	PR
263754	WELL	PR	03/01/2011	GW	045-08137	GIBSON GULCH UNIT 2-30	PR
284608	WELL	PR	05/10/2007	GW	045-12218	GGU DALEY 41B-30-691	PR
284609	WELL	PR	05/12/2007	GW	045-12217	GGU DALEY 44A-19-691	PR
300468	WELL	PR	02/16/2010	GW	045-17905	GGU DALEY 11A-29-691	PR
300469	WELL	PR	02/16/2010	GW	045-17906	GGU DALEY 12C-29-691	PR
300470	WELL	PR	02/16/2010	GW	045-17907	GGU DALEY 11D-29-691	PR
300471	WELL	PR	02/16/2010	GW	045-17908	GGU DALEY 41A-30-691	PR
300472	WELL	PR	02/16/2010	GW	045-17909	GGU DALEY 44B-19-691	PR
300473	WELL	PR	02/16/2010	GW	045-17910	GGU DALEY 41C-30-691	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Separator

0

Comment:

Corrective Action:

Date:

Type: Plunger Lift

10

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

0

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

3

Comment: [Chemical units at wellhead](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

10

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	STEEL AST		39.503969,-107.589276
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity) 375bbbls

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	211391	Type:	WELL	API Number:	045-07151	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	263754	Type:	WELL	API Number:	045-08137	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	284608	Type:	WELL	API Number:	045-12218	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	284609	Type:	WELL	API Number:	045-12217	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300468	Type:	WELL	API Number:	045-17905	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300469	Type:	WELL	API Number:	045-17906	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300470	Type:	WELL	API Number:	045-17907	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	300471	Type:	WELL	API Number:	045-17908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	300472	Type:	WELL	API Number:	045-17909	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	300473	Type:	WELL	API Number:	045-17910	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					
Ditches	Pass					

Comment:

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT