

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2016

Submitted Date:

01/03/2017

Document Number:

666802841**FIELD INSPECTION FORM**

Loc ID 334779	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>24</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289341	WELL	PR		GW	045-13737	HARRIS RWF 431-5	PR
289342	WELL	PR	08/31/2008	GW	045-13736	HARRIS RWF 533-5	PR
289343	WELL	PR		GW	045-13735	HARRIS RWF 333-5	PR
289344	WELL	PR		GW	045-13734	HARRIS RWF 33-5	PR
289345	WELL	PR	10/31/2008	GW	045-13733	HARRIS RWF 433-5	PR
289346	WELL	PR		GW	045-13732	HARRIS RWF 331-5	PR
289347	WELL	PR		GW	045-13731	HARRIS RWF 31-5	PR
289348	WELL	PR		GW	045-13730	HARRIS RWF 332-5	PR
289349	WELL	PR		GW	045-13729	HARRIS RWF 531-5	PR
289350	WELL	PR		GW	045-13728	HARRIS RWF 32-5	PR
289351	WELL	PR		GW	045-13727	HARRIS RWF 432-5	PR
289352	WELL	PR		GW	045-13726	HARRIS RWF 532-5	PR
289353	WELL	PR		GW	045-13725	HARRIS RWF 541-5	PR
289354	WELL	PR		GW	045-13724	HARRIS RWF 341-5	PR
289355	WELL	PR		GW	045-13723	HARRIS RWF 441-5	PR
289356	WELL	PR		GW	045-13722	HARRIS RWF 342-5	PR
289360	WELL	PR		GW	045-13718	HARRIS RWF 43-5	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1912-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Landowners equipment on location		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical units at wellhead		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 17		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 17		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.467807,-107.910244
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	YES
Comment:	Bradenhead valves open
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	289341	Type:	WELL	API Number:	045-13737	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289342	Type:	WELL	API Number:	045-13736	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289343	Type:	WELL	API Number:	045-13735	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289344	Type:	WELL	API Number:	045-13734	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289345	Type:	WELL	API Number:	045-13733	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289346	Type:	WELL	API Number:	045-13732	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289347	Type:	WELL	API Number:	045-13731	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289348	Type:	WELL	API Number:	045-13730	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	289349	Type:	WELL	API Number:	045-13729	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289350	Type:	WELL	API Number:	045-13728	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289351	Type:	WELL	API Number:	045-13727	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289352	Type:	WELL	API Number:	045-13726	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289353	Type:	WELL	API Number:	045-13725	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289354	Type:	WELL	API Number:	045-13724	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289355	Type:	WELL	API Number:	045-13723	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	289356	Type:	WELL	API Number:	045-13722	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	Disconnected
Pilot: OFF	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					

Comment:

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT