

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/26/2016

Submitted Date:

01/03/2017

Document Number:

666802844**FIELD INSPECTION FORM**
 Loc ID 334748 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290549	WELL	PR	02/16/2011	GW	045-14153	WELLS RWF 24-32	PR
290550	WELL	PR	09/28/2008	GW	045-14152	WELLS RWF 424-32	PR
290551	WELL	PR	09/30/2008	GW	045-14151	WELLS RWF 524-32	PR
290552	WELL	PR	05/11/2007	GW	045-14150	WELLS RWF 413-32	PR
290553	WELL	PR	05/11/2007	GW	045-14149	WELLS RWF 313-32	PR
290554	WELL	PR	05/11/2007	GW	045-14148	WELLS RWF 513-32	PR
290555	WELL	PR	05/11/2007	GW	045-14147	WELLS RWF 14-32	PR
290556	WELL	PR	05/11/2007	GW	045-14146	WELLS RWF 314-32	PR
290557	WELL	PR	01/31/2008	GW	045-14145	WELLS RWF 414-32	PR
290558	WELL	PR	05/11/2007	GW	045-14144	WELLS RWF 323-32	PR
290559	WELL	PR	05/11/2007	GW	045-14143	WELLS RWF 23-32	PR
290560	WELL	PR	06/30/2008	GW	045-14142	WELLS RWF 523-32	PR
290561	WELL	PR	09/30/2008	GW	045-14141	WELLS RWF 423-32	PR
290562	WELL	PR	10/19/2008	GW	045-14140	WELLS RWF 324-32	PR
292165	WELL	PR	09/06/2007	GW	045-14611	WELLS RWF 13-32	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-1908-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 15		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Chemical units at wellhead		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at separators		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:	Centralized battery				
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		39.480563,-107.911941	
Comment:						
Corrective Action:				Date:		
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	290549	Type:	WELL	API Number:	045-14153	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290550	Type:	WELL	API Number:	045-14152	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290551	Type:	WELL	API Number:	045-14151	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290552	Type:	WELL	API Number:	045-14150	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290553	Type:	WELL	API Number:	045-14149	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290554	Type:	WELL	API Number:	045-14148	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290555	Type:	WELL	API Number:	045-14147	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290556	Type:	WELL	API Number:	045-14146	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Facility ID:	290557	Type:	WELL	API Number:	045-14145	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290558	Type:	WELL	API Number:	045-14144	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290559	Type:	WELL	API Number:	045-14143	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290560	Type:	WELL	API Number:	045-14142	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290561	Type:	WELL	API Number:	045-14141	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	290562	Type:	WELL	API Number:	045-14140	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			
Facility ID:	292165	Type:	WELL	API Number:	045-14611	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger Lift								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	Disconnected
Pilot: OFF	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Sediment Traps	Pass					
		Ditches	Pass			
Berms	Pass					

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT