

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

666802858**FIELD INSPECTION FORM**

Loc ID 334790 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Findings:**5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211592	WELL	PR	03/22/2004	OW	045-07353	SHIDELER 19-15	TA
271161	WELL	PR	04/01/2013	GW	045-09845	SHIDELER 30-2 (O19E)	PR
276985	WELL	PR	08/06/2005	GW	045-10562	SHIDELER 19-10 (O19E)	PR

General Comment:

Action required items noted on previous inspection have been satisfied, Facilities on location ID 431050

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift

2

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 211592 Type: WELL API Number: 045-07353 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Current Form 4 on file to maintain Temporarily Abandoned well status

Corrective Action: _____ Date: _____

Facility ID: 271161 Type: WELL API Number: 045-09845 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____ Date: _____

Facility ID: 276985 Type: WELL API Number: 045-10562 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____ Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
		Ditches	Pass			
Gravel	Pass					
		Gravel	Pass			
Sediment Traps	Pass					
Seeding	Pass					
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT