



**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type PIT		
Comment:			
Corrective Action:		Date:	

**Equipment:**

					corrective date
Type: Vertical Separator	# 1				
Comment:					
Corrective Action:		Date:			
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:		Date:			
Type: Deadman # & Marked	# 3				
Comment:					
Corrective Action:		Date:			
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 292379 Type: WELL API Number: 071-09396 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type:      Liner Condition:

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type:      Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: 30' x 70'

Corrective Action

Date:

Permit:	Facility ID	Permit Num	Expiration Date
	300920	1941806	

Monitoring:	Monitoring Type	Comment`
	Chain	