

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/04/2017

Submitted Date:

01/04/2017

Document Number:

674004738**FIELD INSPECTION FORM**

Loc ID 329686 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249909	WELL	PR	02/20/1994	OW	123-17712	HICKS 7-15J7	PA

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Leed Rig 724		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 249909 Type: WELL API Number: 123-17712 Status: PR Insp. Status: PA

CementCement ContractorContractor Name: Schlumbeger

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 7100-6354Cement Volume (sx): 25 SacksGood Return During Job: YESCement Type: Type GComment: Routine Niobrara coverage

Corrective Action: _____

Date: _____

WorkoverComment: LEED 724

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<u>Routine PA</u> <u>Compay representative on location: Jay Chandler.</u>	carlilec	01/04/2017