

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2017

Submitted Date:

01/09/2017

Document Number:

666802871**FIELD INSPECTION FORM**

Loc ID 334670 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257436	WELL	PR	12/31/2004	GW	045-07563	MILLER 2-10	PR
271322	WELL	PR	01/05/2005	GW	045-09863	CEDAR SPRINGS RANCH 2-14A (J2W)	PR
271323	WELL	PR	12/22/2005	GW	045-09864	CEDAR SPRINGS RANCH 2-11A2 (J2W)	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0850-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	OTHER	STEEL AST		39.473149,-107.742095
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	250bbbls	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 257436 Type: WELL API Number: 045-07563 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 271322 Type: WELL API Number: 045-09863 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 271323 Type: WELL API Number: 045-09864 Status: PR Insp. Status: PR**Producing Well**Comment: Plunger lift

Corrective Action:

Date:

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT