

Reclamation Inspection

01/09/2017

Operator: Atlas Resources LLC

Location ID: 425447

Phillips County, CO

SWNW Section 34 T9N R43W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO

Department of Natural Resources



Figure 1: Photo of GPS confirming location.



Figure 2: Photo taken from the northeast end of the location, facing west. Photo shows interim and project areas.



Figure 3: Photo taken from the northeast end of the location, facing south. Photo shows interim and project areas.



Figure 4: Photo taken from the northwest end of the location, facing east. Photo shows interim and project areas.



Figure 5: Photo taken from the northwest end of the location, facing south. Photo shows interim and project areas.



Figure 6: Photo taken from the southwest end of the location, facing east. Photo shows interim and project areas.



Figure 7: Photo taken from the southwest end of the location, facing north. Photo shows interim and project areas.



Figure 8: Photo taken from the southeast end of the location, facing west. Photo shows interim and project areas.



01.09.2017 10:13

Figure 9: Photo taken from the southeast end of the location, facing north. Photo shows interim and project areas.



Figure 10: Photo taken from the southeast end of the interim area. Photo shows disturbance quadrat #1



095-06208
1/9/17
Dist #2

01.09.2017 10:23

Figure 11: Photo taken from the south end of the interim area. Photo shows disturbance quadrat #2



095-06208
1/9/17
Dist #3

01.09.2017 10:29

Figure 12: Photo taken from the west end of the interim area. Photo shows disturbance quadrat #3



Figure 13: Photo taken from the reference area, south of the location. Photo shows Reference quadrat #1



095-06208
11/9/17
Ref #2

01.09.2017 10:38

Figure 14: Photo taken from the reference area, south of the location. Photo shows Reference quadrat #2