

Photo#1:

View West up Access Road into Location .



Photo#2:

View East of Access Road exiting Location.



Photo#3:



Photo#4:

Concrete Vault on Location



January 10, 2017

Inspection Photos: Encana BJM Disposal 1 API# 045-07463

Photo#5:



Photo#6:

Vegetation appears Vigorous and Well established.

