

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#				corrective date
Type: Gas Meter Run	# 2				
Type: Horizontal Heated Separator	# 2				
Type: Plunger Lift	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		39.535476,-107.840530	

Paint

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210460 Type: WELL API Number: 045-06216 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 210468 Type: WELL API Number: 045-06224 Status: PR Insp. Status: PR

Producing Well

Comment: Producing

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Retention Ponds	Pass			
Seeding	Pass					
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT