

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/06/2017

Submitted Date:

01/06/2017

Document Number:

674703508**FIELD INSPECTION FORM**

Loc ID 334772	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>16</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210758	WELL	PR	10/23/1986	GW	045-06516	DERE W-24-35	PR
210893	WELL	PR	05/03/1998	GW	045-06651	DERE GV 47-35	PR
281506	WELL	PR	04/11/2007	GW	045-11472	DERE PA 23-35	PR
281508	WELL	PR	07/08/2009	GW	045-11473	DERE PA 323-35	PR
288848	WELL	PR	01/10/2007	GW	045-13612	DERE/JENSEN PA 13-35	PR
288857	WELL	PR	01/10/2007	GW	045-13611	DERE/JENSEN PA313-35	PR
288858	WELL	PR	01/10/2007	GW	045-13610	DERE/JENSEN PA413-35	PR
288859	WELL	PR	01/10/2007	GW	045-13609	DERE/JENSEN PA 513-35	PR
288860	WELL	PR	01/10/2007	GW	045-13608	DERE/JENSEN PA 24-35	PR
288861	WELL	PR	01/10/2007	GW	045-13607	DERE/JENSEN PA 423-35	PR
288862	WELL	PR	01/10/2007	GW	045-13606	DERE/JENSEN PA 523-35	PR
288863	WELL	PR	01/10/2007	GW	045-13605	DERE/JENSEN PA514-35	PR
288864	WELL	PR	01/10/2007	GW	045-13604	DERE/JENSEN PA 314-35	PR
288865	WELL	PR	01/10/2007	GW	045-13603	DERE/JENSEN PA414-35	PR

General Comment:

317B Intermediate Buffer (301'-500')

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 14		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	210758	Type:	WELL	API Number:	045-06516	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	210893	Type:	WELL	API Number:	045-06651	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281506	Type:	WELL	API Number:	045-11472	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	281508	Type:	WELL	API Number:	045-11473	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288848	Type:	WELL	API Number:	045-13612	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288857	Type:	WELL	API Number:	045-13611	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288858	Type:	WELL	API Number:	045-13610	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288859	Type:	WELL	API Number:	045-13609	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 288860	Type: WELL	API Number: 045-13608	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288861	Type: WELL	API Number: 045-13607	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288862	Type: WELL	API Number: 045-13606	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288863	Type: WELL	API Number: 045-13605	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288864	Type: WELL	API Number: 045-13604	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 288865	Type: WELL	API Number: 045-13603	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401179892	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4046460