



Photo#1: There is no evidence of the AL Wells on this Active Location.

January 16, 2017

Inspection Photos: Encana Rose Ranch Loc#334583 ALs



Photo#2: There is no evidence of the AL Wells on this Active Location.

January 16, 2017

Inspection Photos: Encana Rose Ranch Loc#334583 ALs



Photo#: View over GPS Position of AL Wells (indicated by Arrow) in Interim Reclamation Area.

Inspection Photos: Encana Rose Ranch Loc#334583 ALs

January 16, 2017