

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/18/2017  
Submitted Date:  
01/18/2017  
Document Number:  
684902952

**FIELD INSPECTION FORM**

Loc ID 318343 Inspector Name: Pesicka, Conor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: K P KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name      | Phone        | Email         | Comment                         |
|-------------------|--------------|---------------|---------------------------------|
| Lara-Mesa, Susana | 303-825-4822 | cogcc@kpk.com | <a href="#">All inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 241142      | WELL | PR     | 03/20/1995  | GW         | 123-08930 | YOXALL FARMS 4 | PR          |

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Equipment:**

| Type               | #   | Capacity | Type | Tank ID | SE GPS | corrective date |
|--------------------|-----|----------|------|---------|--------|-----------------|
| Type: Pump Jack    | # 1 |          |      |         |        |                 |
| Comment:           |     |          |      |         |        |                 |
| Corrective Action: |     | Date:    |      |         |        |                 |
| Type: Prime Mover  | # 1 |          |      |         |        |                 |
| Comment: electric  |     |          |      |         |        |                 |
| Corrective Action: |     | Date:    |      |         |        |                 |

**Tanks and Berms:**

| Contents           | #                                 | Capacity | Type                | Tank ID | SE GPS |  |
|--------------------|-----------------------------------|----------|---------------------|---------|--------|--|
|                    |                                   |          | CENTRALIZED BATTERY |         |        |  |
| Comment:           | Spindle Consolidation Facility #7 |          |                     |         |        |  |
| Corrective Action: |                                   | Date:    |                     |         |        |  |

**Paint**

|                  |  |  |  |
|------------------|--|--|--|
| Condition        |  |  |  |
| Other (Content)  |  |  |  |
| Other (Capacity) |  |  |  |
| Other (Type)     |  |  |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |  |
|------|----------|---------------------|---------------------|-------------|--|
|      |          |                     |                     |             |  |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

Facility ID: 241142 Type: WELL API Number: 123-08930 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR sales gas

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead plumbed to surface

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT