

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2017

Submitted Date:

01/17/2017

Document Number:

674703540**FIELD INSPECTION FORM**
 Loc ID 335088 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 211064      | WELL | PR     | 01/26/2015  | GW         | 045-06822 | CHEVRON MV 55-29  | PR          |
| 260718      | WELL | PR     | 11/19/2001  | GW         | 045-07903 | CHEVRON GM 22-29  | PR          |
| 282720      | WELL | PR     | 03/18/2006  | GW         | 045-11803 | CHEVRON GM 421-29 | PR          |
| 282721      | WELL | PR     | 04/11/2006  | GW         | 045-11802 | CHEVRON GM 321-29 | PR          |

**General Comment:**

**Location**

|                    |                     |       |  |
|--------------------|---------------------|-------|--|
| <b>Lease Road:</b> |                     |       |  |
| Type               | Access              |       |  |
| comment:           | Snow covered/packed |       |  |
| Corrective Action  | L                   | Date: |  |

Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| <b>Equipment:</b>  |     |       | corrective date |
| Type: Plunger Lift | # 4 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

|                                   |     |  |       |
|-----------------------------------|-----|--|-------|
| Type: Bird Protectors             | # 5 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Horizontal Heated Separator | # 4 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |
| Type: Dehydrator                  | # 1 |  |       |
| Comment:                          |     |  |       |
| Corrective Action:                |     |  | Date: |

**Tanks and Berms:**

|                    |   |           |           |         |        |       |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents           | # | Capacity  | Type      | Tank ID | SE GPS |       |
| PRODUCED WATER     | 1 | <100 BBLs | STEEL AST |         | ,      |       |
| Comment:           |   |           |           |         |        |       |
| Corrective Action: |   |           |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbl   |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                |       |      |             |           |         |    |               |    |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 211064         | Type: | WELL | API Number: | 045-06822 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 260718         | Type: | WELL | API Number: | 045-07903 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 282720         | Type: | WELL | API Number: | 045-11803 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |
|                       |                |       |      |             |           |         |    |               |    |
| Facility ID:          | 282721         | Type: | WELL | API Number: | 045-11802 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                |       |      |             |           |         |    |               |    |
| Comment:              | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:    |                |       |      |             |           | Date:   |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Limited inspection due to snow cover.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT