



photo 1: Facing northwest toward the location. There is little to no vegetation establishment.



photo 2: West side of the location facing east. The soil color appears to be different from the soils outside of the location.



photo 3: Groundcover off the location in the undisturbed pasture.



photo 4: Facing north toward the surrounding undisturbed pasture (reference area).