



photo 1: Facing northeast along the former access road.



photo 2: The soils along the access road seem to be compacted and vegetation has not established.



photo 3: Center of the location facing north.



photo 4: Center of the location facing west.



photo 5: Center of the location facing south.



photo 6: Center of the location facing east.