

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2017

Submitted Date:

01/17/2017

Document Number:

673403984**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 313125 Waldron, Emily 2A Doc Num: _____

Operator Information:OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223607	WELL	PR	08/10/2001	GW	081-07014	MUSSER, B W 10	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-341-3129

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

CONDENSATE	1	400 BBLs	HEATED STEEL AST		40.940280,-108.298570	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate			Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate			Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities				
Facility ID: 223607	Type: WELL	API Number: 081-07014	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT