

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/19/2017

Submitted Date:

01/19/2017

Document Number:

675203777**FIELD INSPECTION FORM**
 Loc ID 426123 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426125	WELL	PR	01/31/2013	GW	045-21126	Bosely SG 542-23	PR
426128	WELL	PR	02/13/2013	GW	045-21127	Bosely SG 442-23	PR
426132	WELL	PR	01/28/2013	GW	045-21128	Bosely SG 33-23	PR
426133	WELL	PR	01/28/2013	GW	045-21129	Bosely SG 42-23	PR
426141	WELL	PR	02/13/2013	GW	045-21130	Bosely SG 342-23	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>426125</u>	Type: <u>WELL</u>	API Number: <u>045-21126</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426128</u>	Type: <u>WELL</u>	API Number: <u>045-21127</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426132</u>	Type: <u>WELL</u>	API Number: <u>045-21128</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426133</u>	Type: <u>WELL</u>	API Number: <u>045-21129</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>426141</u>	Type: <u>WELL</u>	API Number: <u>045-21130</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT