

# Reclamation Inspection

01/19/2017

Operator: Chandler & Associates LLC (QEP)

Location ID: 378092

Arapahoe County, CO

NWNW Section 29 T4S R64W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**

Department of Natural Resources



**Figure 1:** Photo of GPS confirming location.



**Figure 2:** Photo taken from the south end of the location, facing west. Photo shows reclamation in process.



**Figure 3:** Photo taken from the south end of the location, facing northwest. Photo shows reclamation in process.



**Figure 4:** Photo taken from the south end of the location, facing north. Photo shows reclamation in process.



**Figure 5:** Photo taken from the south end of the location, facing east. Photo shows reclamation in process.