

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Ancillary equipment		
Comment: APPROX 32' SOUND WALLS		
Corrective Action:		Date: <input type="text"/>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: 444953 Type: WELL API Number: 123-42823 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: ENSIGN 152 Pusher/Rig Manager: JEREMY STOLZ
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: WAST MANAGEMENT

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 444958 Type: WELL API Number: 123-42828 Status: DG Insp. Status: DG

Facility ID: 444962 Type: WELL API Number: 123-42832 Status: DG Insp. Status: DG

Facility ID: 444963 Type: WELL API Number: 123-42833 Status: DG Insp. Status: DG

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT