

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
01/23/2017
Submitted Date:
01/23/2017
Document Number:
672500344

FIELD INSPECTION FORM

Loc ID 332241 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1625 BROADWAY STE 2200
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271336	WELL	PR	12/26/2004	OW	123-22025	EISENSTAT 22-21	PA

General Comment:

(This area is intentionally left blank for general comments.)

Inspected Facilities

Facility ID: 271336 Type: WELL API Number: 123-22025 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): 83

Circulate to Surface: YES

Cement Fall Back: _____

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 865'

Cement Volume (sx): 83

Good Return During Job: YES

Cement Type: G-NEAT

Comment: CMT. PRESSURE TEST LINES. PUMP 83 SX (17 BBLs) 15.8 PPG CLASS G NEAT
CMT FORM 865' - SURFACE

Corrective Action:

Date: _____

Workover

Comment: P&A

Corrective Action:

Date: _____