



**Inspected Facilities**

Facility ID: 295296 Type: WELL API Number: 057-06465 Status: PR Insp. Status: PR

**Workover**

Comment: Workover on location replacing drip pot.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	295300	1433849	
	298265	1433924	
	298265	1433924	