

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2017

Submitted Date:

01/30/2017

Document Number:

666802923

FIELD INSPECTION FORM

Loc ID 334572 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211485	WELL	PR	10/16/2003	GW	045-07245	SAVAGE 1-34	PR
276681	WELL	PR	02/01/2013	GW	045-10511	SAVAGE FEDERAL 1-9A (R11)	SI
276682	WELL	PR	07/23/2005	GW	045-10510	SAVAGE FEDERAL 1-9D (R11)	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: STORAGE OF SUPL

Comment: [Portable heater](#)

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Ancillary equipment # 1

Comment: [Chimical unit at wellhead](#)

Corrective Action:

Date:

Type: Gas Meter Run # 3

Comment:

Corrective Action:

Date:

Type: Plunger Lift # 3

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator # 3

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,

Comment: [Centralized battery](#)

Corrective Action:

Date:

Paint

Condition: Adequate

Other (Content):

Other (Capacity):

Other (Type):

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		39.467062,-107.827597
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 211485 Type: WELL API Number: 045-07245 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 276681 Type: WELL API Number: 045-10511 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: Last production numbers posted Nov 2016

Corrective Action:

Date: _____

Facility ID: 276682 Type: WELL API Number: 045-10510 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Snow covered access road and location](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT