

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

01/30/2017

Document Number:

666802925**FIELD INSPECTION FORM**

Loc ID 323874 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone | Email                              | Comment                           |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections |       | COGCCInspectionReports@terraep.com | <a href="#">Field Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 211060      | WELL | PR     | 11/17/1994  | GW         | 045-06818 | YOUBERG RU 11-7 | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment: [Chemical unit at wellhead](#)

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

| Contents | # | Capacity | Type      | Tank ID | SE GPS |
|----------|---|----------|-----------|---------|--------|
| METHANOL | 1 | OTHER    | STEEL AST |         | ,      |

Comment: [At separators](#)

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity) 500gal

Other (Type)

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

|                    |          |                     |                     |             |                       |       |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|-------|
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| CONDENSATE         | 1        | 300 BBLs            | STEEL AST           |             | 39.459506,-107.824427 |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <u>Paint</u>       |          |                     |                     |             |                       |       |
| Condition          | Adequate |                     |                     |             |                       |       |
| Other (Content)    |          |                     |                     |             |                       |       |
| Other (Capacity)   |          |                     |                     |             |                       |       |
| Other (Type)       |          |                     |                     |             |                       |       |
| <u>Berms</u>       |          |                     |                     |             |                       |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| Contents           | #        | Capacity            | Type                | Tank ID     | SE GPS                |       |
| PRODUCED WATER     | 1        | 200 BBLs            | STEEL AST           |             | ,                     |       |
| Comment:           |          | Centralized battery |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <u>Paint</u>       |          |                     |                     |             |                       |       |
| Condition          | Adequate |                     |                     |             |                       |       |
| Other (Content)    |          |                     |                     |             |                       |       |
| Other (Capacity)   |          |                     |                     |             |                       |       |
| Other (Type)       |          |                     |                     |             |                       |       |
| <u>Berms</u>       |          |                     |                     |             |                       |       |
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |                       |       |
|                    |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <u>Venting:</u>    |          |                     |                     |             |                       |       |
| Yes/No             | NO       |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |
| <u>Flaring:</u>    |          |                     |                     |             |                       |       |
| Type               |          |                     |                     |             |                       |       |
| Comment:           |          |                     |                     |             |                       |       |
| Corrective Action: |          |                     |                     |             |                       | Date: |

|                             |              |                       |            |                  |
|-----------------------------|--------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |              |                       |            |                  |
| Facility ID: 211060         | Type: WELL   | API Number: 045-06818 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |              |                       |            |                  |
| Comment:                    | Plunger lift |                       |            |                  |
| Corrective Action:          |              |                       |            | Date:            |

|  |  |  |  |  |
|--|--|--|--|--|
|  |  |  |  |  |
|--|--|--|--|--|

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: 

Snow covered access road and location

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT