

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/31/2017  
Submitted Date:  
01/31/2017  
Document Number:  
681901979

**FIELD INSPECTION FORM**

Loc ID 331995 Inspector Name: HELGELAND, GARY On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

15 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
|              |       | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269523      | WELL | PR     | 07/15/2010  | OW         | 123-21690 | BLC 8-2A      | PR          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

|                    |                      |  |       |
|--------------------|----------------------|--|-------|
| Type               | TANK LABELS/PLACARDS |  |       |
| Comment:           | SATISFACTORY         |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | BATTERY              |  |       |
| Comment:           | SATISFACTORY         |  |       |
| Corrective Action: |                      |  | Date: |
| Type               | WELLHEAD             |  |       |
| Comment:           | SATISFACTORY         |  |       |
| Corrective Action: |                      |  | Date: |

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                    |  |       |
|--------------------|--------------------|--|-------|
| Type               | WELLHEAD           |  |       |
| Comment:           | Privacy chain link |  |       |
| Corrective Action: |                    |  | Date: |
| Type               | TANK BATTERY       |  |       |
| Comment:           | Privacy chain link |  |       |
| Corrective Action: |                    |  | Date: |

**Equipment:**

| Type                              |              |  | corrective date |
|-----------------------------------|--------------|--|-----------------|
| Type: Gas Meter Run               | # 1          |  |                 |
| Comment:                          | SATISFACTORY |  |                 |
| Corrective Action:                |              |  | Date:           |
| Type: Bird Protectors             | # 2          |  |                 |
| Comment:                          | SATISFACTORY |  |                 |
| Corrective Action:                |              |  | Date:           |
| Type: Plunger Lift                | # 1          |  |                 |
| Comment:                          | SATISFACTORY |  |                 |
| Corrective Action:                |              |  | Date:           |
| Type: Horizontal Heated Separator | # 1          |  |                 |

|                               |              |  |       |  |
|-------------------------------|--------------|--|-------|--|
| Comment:                      | SATISFACTORY |  | Date: |  |
| Corrective Action:            |              |  | Date: |  |
| Type: Emission Control Device | # 1          |  |       |  |
| Comment:                      | SATISFACTORY |  | Date: |  |
| Corrective Action:            |              |  | Date: |  |
| Type: Pig Station             | # 1          |  |       |  |
| Comment:                      | SATISFACTORY |  | Date: |  |
| Corrective Action:            |              |  | Date: |  |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type           | Tank ID | SE GPS |
|--------------------|---|-----------|----------------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLs | PBV FIBERGLASS |         |        |
| Comment:           |   |           |                |         | Date:  |
| Corrective Action: |   |           |                |         | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL          | 1 | OTHER    | STEEL AST |         | 40.168379,-104.964875 |
| Comment:           |   |          |           |         | Date:                 |
| Corrective Action: |   |          |           |         | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 315 bbl  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     | Date:       |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |  |
|--------|----|--|
| Yes/No | NO |  |
|--------|----|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 269523 Type: WELL API Number: 123-21690 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Comment: Bradenhead is plumed to surface.

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT