

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2017

Submitted Date:

01/25/2017

Document Number:

672500371**FIELD INSPECTION FORM**

Loc ID 310874 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------|
| , | | NBL_DJBU_Inspections@NB LENERGY.COM | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 297525 | WELL | PR | 10/23/2008 | OW | 123-27169 | DPG F 1-24 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | AG PANEL | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.423060,-104.617330 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|--|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|--------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297525 | Type: | WELL | API Number: | 123-27169 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | PLUMBED TO SURFACE | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? PassSegregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-CroplandTop soil replaced PassRecontoured Pass

80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401193938 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4059952 |