

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
01/30/2017  
Submitted Date:  
02/01/2017  
Document Number:  
685302172

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: St John, William (Cal) On-Site Inspection   
326496 \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	<a href="#">SW Inspection Reports</a>
Hixon, Logan	505-386-8018	logan_hixon@xtoenergy.com	<a href="#">SW EHS Tech</a>
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89098	WELL	PR	06/07/2001	GW	067-08202	HUBER-LALONDE 4-31	PR

**General Comment:**

*(This area is intentionally left blank for general comments.)*

Location				
<b>Lease Road:</b>				
	Type Access			
comment:				
Corrective ActionL				Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type WELLHEAD			
Comment:				
Corrective Action:				Date:
<b>Emergency Contact Number:</b>				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type WELLHEAD			
Comment:	Panel			
Corrective Action:				Date:
	Type PUMP JACK			
Comment:	Safety Rails with Steel Mesh Barrier.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Ancillary equipment	# 1			corrective date
Comment:	Wellhead			
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Lube Oil Tank on Spill Prevention.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:				
Corrective Action:				Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural Gas Motor		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Sound Walls		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry Equipment		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 89098 Type: WELL API Number: 067-08202 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Location covered in snow at time of inspection.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT