

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2017

Submitted Date:

02/02/2017

Document Number:

666802928**FIELD INSPECTION FORM**

Loc ID 335539	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b>  <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 11 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b>  OGCC Operator Number: <u>10447</u>  Name of Operator: <u>URSA OPERATING COMPANY LLC</u>  Address: <u>1050 17TH STREET #1700</u>  City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80265</u>				

**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291673	WELL	PR	06/11/2013	GW	045-14477	MCPHERSON A3	PR
291679	WELL	PR	05/22/2012	GW	045-14475	McPherson A8	PR
291680	WELL	PR	06/11/2013	GW	045-14476	MCPHERSON A4	PR
298100	WELL	PR	05/17/2012	GW	045-17067	McPherson A6	PR
298101	WELL	PR	06/11/2013	GW	045-17068	MCPHERSON A9	PR
298102	WELL	PR	06/11/2013	GW	045-17069	MCPHERSON A2	PR
298103	WELL	PR	05/23/2012	GW	045-17070	McPherson A12	PR
298104	WELL	PR	05/25/2012	OW	045-17071	McPherson A11	PR
298105	WELL	PR	05/22/2012	GW	045-17072	McPherson A7	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

# 9

Comment:

Corrective Action:

Date:

Type: Emission Control Device

# 2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 9

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment: Centralized battery					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
CONDENSATE		2	300 BBLS	STEEL AST				39.531032,-107.676135		
Comment:										

Corrective Action:					Date:	
--------------------	--	--	--	--	-------	--

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291673	Type:	WELL	API Number:	045-14477	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291679	Type:	WELL	API Number:	045-14475	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	291680	Type:	WELL	API Number:	045-14476	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298100	Type:	WELL	API Number:	045-17067	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298101	Type:	WELL	API Number:	045-17068	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298102	Type:	WELL	API Number:	045-17069	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298103	Type:	WELL	API Number:	045-17070	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	298104	Type:	WELL	API Number:	045-17071	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:						Date:			



## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment: 2 ECB

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Gravel	Pass			
Seeding	In Process					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT