

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
02/02/2017
Submitted Date:
02/02/2017
Document Number:
675103312

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: GRANAHAN, KYLE On-Site Inspection
315281 _____ 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
4 _____ Number of Comments
0 _____ Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
OGCC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 25231 GROGAN'S MILL RD STE 500
City: THE WOODLANDS State: TX Zip: 77380

Contact Information:

Contact Name	Phone	Email	Comment
Clavenna, Mark	281-362-8600 X22	mclavenna@nclnr.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230561	WELL	PR	11/29/1978	GW	103-08229	FORK UNIT-FEDERAL 6-15-1-2	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230561 Type: WELL API Number: 103-08229 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - no leaks/venting](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING Pass

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION Pass

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT