



Photo#1: View South over Location; Well not Drilled or Location Constructed.

Inspection Photos: TEP AL Chevron GM API#045-09289

January 31, 2017





Photo#2: View West; there is No Evidence of Well or Planned Location.

Inspection Photos: TEP AL Chevron GM API#045-09289

January 31, 2017