

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
02/09/2017  
Submitted Date:  
02/09/2017  
Document Number:  
674103928

**FIELD INSPECTION FORM**

Loc ID 332882 Inspector Name: Rickard, Jeff On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, General		COGCCinspections@Anadarko.com	
Adamczyk, Megan		megan.adamczyk@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443821	WELL	DG	05/21/2016	LO	123-42389	LAND 14N-32HZ	WK
443822	WELL	DG	05/22/2016	LO	123-42390	LAND FED 3N-32HZ	WK
443823	WELL	DG	05/24/2016	LO	123-42391	LAND FED 13S-32HZ	WK
443824	WELL	DG	05/19/2016	LO	123-42392	LAND FED 35N-29HZ	WK
443825	WELL	DG	05/16/2016	LO	123-42393	LAND FED 29N-29HZ	WK
443826	WELL	DG	05/20/2016	LO	123-42394	LAND 28N-29HZ	WK
443827	WELL	DG	05/15/2016	LO	123-42395	LAND FED 34C-32HZ	WK
443828	WELL	DG	05/26/2016	LO	123-42396	LAND FED 34N-32HZ	WK
443829	WELL	DG	05/18/2016	LO	123-42397	LAND FED 35C-32HZ	WK
443830	WELL	DG	05/25/2016	LO	123-42398	LAND FED 30N-29HZ	WK
443831	WELL	DG	05/23/2016	LO	123-42399	LAND FED 29C-29HZ	WK
443832	WELL	DG	05/17/2016	LO	123-42400	LAND FED 13N-32HZ	WK
443833	WELL	DG	05/14/2016	LO	123-42401	LAND FED 30C-29HZ	WK

**General Comment:**

**Inspected Facilities**

Facility ID: 443821 Type: WELL API Number: 123-42389 Status: DG Insp. Status: WK

**Complaint**

Comment: [Complaint #:200441031](#)  
 Field Inspector Assigned: Jeff Rickard  
 Location #: 332882  
 Inspection Document #: 674103928  
 Nature of complaint: Sound  
 If Sound GPS Coordinates of Survey Location: N/A  
 Inspection Observations:  
 OGCC inspector returned to location to try and run a sound survey. Current wind conditions were sustained winds out of the south of 7-9mph, with gusts every 3 to 5 minutes of 12-14mph. Since wind conditions were above the 5mph limit for a valid sound survey, a survey was not run. Current weather forecast call for winds to increase as the day goes on. OGCC inspector will return tomorrow 2/10/17 to try and run a sound survey if wind conditions are appropriate.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC  
 Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
 Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
 Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
 Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: [Braden head is exposed at surface.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 443822 Type: WELL API Number: 123-42390 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC  
 Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
 Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
 Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
 Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443823 Type: WELL API Number: 123-42391 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type:

**Observation:**

Other:

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443824 Type: WELL API Number: 123-42392 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

**Observation:**

Other:

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443825 Type: WELL API Number: 123-42393 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 443826 Type: WELL API Number: 123-42394 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 443827 Type: WELL API Number: 123-42395 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI Tubing: \_\_\_\_\_  
Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
Bradenhead Psi: \_\_\_\_\_ Frac Flow Back: \_\_\_\_\_ Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443828 Type: WELL API Number: 123-42396 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other:

**Observation:**

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443829 Type: WELL API Number: 123-42397 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other:

**Observation:**

Maximum Casing Recorded: PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action:

Date:

Facility ID: 443830 Type: WELL API Number: 123-42398 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: \_\_\_\_\_

Fluid: \_\_\_\_\_

Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 443831 Type: WELL API Number: 123-42399 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: \_\_\_\_\_

Fluid: \_\_\_\_\_

Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Braden head is exposed at surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 443832 Type: WELL API Number: 123-42400 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: \_\_\_\_\_ PSI

Tubing: \_\_\_\_\_

Surface: \_\_\_\_\_

Intermediate: \_\_\_\_\_

Production: \_\_\_\_\_

Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_

Bradenhead Psi: \_\_\_\_\_

Frac Flow Back: \_\_\_\_\_

Fluid: \_\_\_\_\_

Gas: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment:

Corrective Action:

Date:

Facility ID: 443833 Type: WELL API Number: 123-42401 Status: DG Insp. Status: WK

**Well Stimulation**

Stimulation Company: Cal Frac

Stimulation Type: HYDRAULIC FRAC

Other:

**Observation:**

Maximum Casing Recorded:  PSI

Tubing:

Surface:

Intermediate:

Production:

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

**BradenHead**

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>Complaint #:200441031</p> <p>Field Inspector Assigned: Jeff Rickard</p> <p>Location #: 332882</p> <p>Inspection Document #: 674103928</p> <p>Nature of complaint: Sound</p> <p>If Sound GPS Coordinates of Survey Location: N/A</p> <p>Inspection Observations:</p> <p>OGCC inspector returned to location to try and run a sound survey. Current wind conditions were sustained winds out of the south of 7-9mph, with gusts every 3 to 5 minutes of 12-14mph. Since wind conditions were above the 5mph limit for a valid sound survey, a survey was not run. Current weather forecast call for winds to increase as the day goes on. OGCC inspector will return tomorrow 2/10/17 to try and run a sound survey if wind conditions are appropriate.</p>	rickardj	02/09/2017