

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

02/09/2017

Document Number:

675203798**FIELD INSPECTION FORM**

Loc ID 334113	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				<b>Findings:</b> <u>2</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292775	WELL	PR	04/30/2008	GW	045-14748	BOSELY SG 44/27	PR
293568	WELL	PR	11/19/2007	GW	045-15052	BOSLEY SG 344-27	PR
293569	WELL	PR	11/20/2007	GW	045-15054	BOSELY SG 341-34	PR
293570	WELL	PR	01/31/2009	GW	045-15055	BOSELY SG 41-34	PR
293571	WELL	PR	11/20/2007	GW	045-15056	BOSELY SG 544-27	PR
293572	WELL	PR	11/20/2007	GW	045-15057	BOSELY SG 541-34	PR
293574	WELL	PR	11/20/2007	GW	045-15053	BOSELY SG 441-34	PR
293579	WELL	PR	11/20/2007	GW	045-15058	BOSELY SG 444-27	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>292775</u>	Type:	<u>WELL</u>	API Number:	<u>045-14748</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293568</u>	Type:	<u>WELL</u>	API Number:	<u>045-15052</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293569</u>	Type:	<u>WELL</u>	API Number:	<u>045-15054</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293570</u>	Type:	<u>WELL</u>	API Number:	<u>045-15055</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293571</u>	Type:	<u>WELL</u>	API Number:	<u>045-15056</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293572</u>	Type:	<u>WELL</u>	API Number:	<u>045-15057</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293574</u>	Type:	<u>WELL</u>	API Number:	<u>045-15053</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>293579</u>	Type:	<u>WELL</u>	API Number:	<u>045-15058</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel	Pass			
Compaction		Compaction	Pass			

Comment: [Rutting on location. See attached photo.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203799	BoselySG 1-30-17	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4071845">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4071845</a>