

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

02/09/2017

Document Number:

675203801**FIELD INSPECTION FORM**
 Loc ID 334359 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285098	WELL	PR	02/01/2011	GW	045-12376	REPP0 A11-34B	PR
286086	WELL	PR	01/12/2010	GW	045-12614	REPP0 A-10-34D	PR
295579	WELL	PR	03/30/2009	GW	045-15791	REPP0 34-7D	PR
295580	WELL	PR	02/18/2010	GW	045-15790	REPP0 34-11C	PR
295582	WELL	PR	01/27/2010	GW	045-15788	REPP0 34-7B	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: <u>285098</u>	Type: <u>WELL</u>	API Number: <u>045-12376</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>286086</u>	Type: <u>WELL</u>	API Number: <u>045-12614</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>295579</u>	Type: <u>WELL</u>	API Number: <u>045-15791</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>295580</u>	Type: <u>WELL</u>	API Number: <u>045-15790</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>295582</u>	Type: <u>WELL</u>	API Number: <u>045-15788</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT