

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

02/09/2017

Document Number:

675203803**FIELD INSPECTION FORM**
 Loc ID 334621 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283216	WELL	PR	05/14/2007	GW	045-11915	BOSELY SG 443-27	PR
283291	WELL	PR	05/14/2007	GW	045-11912	BOSELY SG 343-27	PR
283292	WELL	PR	03/24/2006	GW	045-11913	BOSELY SG 43-27	PR
283293	WELL	PR	02/16/2006	GW	045-11914	BOSELY SG 543-27	PR
423072	WELL	PR	10/01/2012	GW	045-20657	Bosely SG 42-27	PR
423092	WELL	PR	02/02/2012	GW	045-20669	Bosely SG 541-27	PR
423102	WELL	PR	03/14/2012	GW	045-20674	Bosely SG 342-27	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: <u>283216</u>	Type: <u>WELL</u>	API Number: <u>045-11915</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283291</u>	Type: <u>WELL</u>	API Number: <u>045-11912</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283292</u>	Type: <u>WELL</u>	API Number: <u>045-11913</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283293</u>	Type: <u>WELL</u>	API Number: <u>045-11914</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>423072</u>	Type: <u>WELL</u>	API Number: <u>045-20657</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>423092</u>	Type: <u>WELL</u>	API Number: <u>045-20669</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>423102</u>	Type: <u>WELL</u>	API Number: <u>045-20674</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT