

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2017

Submitted Date:

02/09/2017

Document Number:

668005167**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 333730      DURAN, JOHN      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING      State: TX      Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                     | Comment                         |
|-----------------------|--------------|---------------------------|---------------------------------|
| Distribution, Pioneer | 972-444-9001 | COGCC.Inspections@pxd.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 276193      | WELL | TA     | 03/19/2015  | GW         | 071-08318 | KING 22-13    | TA          |
| 279054      | WELL | PR     | 10/07/2005  | GW         | 071-08465 | KING 22-13 TR | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  | Date: _____ |
| Corrective Action: |  |             |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                          |     |       |                 |
|--------------------------|-----|-------|-----------------|
|                          |     |       | corrective date |
| Type: Gas Meter Run      | # 2 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Deadman # & Marked | # 8 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Vertical Separator | # 2 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |
| Type: Progressive Cavity | # 2 |       |                 |
| Comment:                 |     |       |                 |
| Corrective Action:       |     | Date: |                 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 276193 Type: WELL API Number: 071-08318 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Passed MiT on (03/05/15).

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 279054 Type: WELL API Number: 071-08465 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'Corrective Action: Date: 

| Permit: | Facility ID | Permit Num | Expiration Date      |
|---------|-------------|------------|----------------------|
|         | 282891      | 1490643    | <input type="text"/> |

| Monitoring: | Monitoring Type | Comment`             |
|-------------|-----------------|----------------------|
|             | Chain           | <input type="text"/> |