

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2017

Submitted Date:

02/09/2017

Document Number:

675203810**FIELD INSPECTION FORM**
 Loc ID 335042 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
TEP, Energy		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283419	WELL	PR	07/31/2010	GW	045-11921	FEDERAL SG 341-26	PR
283420	WELL	PR	07/31/2010	GW	045-11923	FEDERAL SG 541-26	PR
283421	WELL	PR	07/31/2010	GW	045-11922	FEDERAL SG 41-26	PR
283422	WELL	PR	07/31/2010	GW	045-11920	FEDERAL SG 441-26	PR
296293	WELL	PR	07/31/2010	GW	045-15976	FEDERAL SG 42-26	PR
296294	WELL	PR	07/31/2010	GW	045-15977	FEDERAL SG 442-26	PR
296295	WELL	PR	07/31/2010	GW	045-15978	FEDERAL SG 342-26	PR
296296	WELL	PR	07/31/2010	GW	045-15979	FEDERAL SG 542-26	PR
412012	WELL	PR	01/11/2010	GW	045-18419	FEDERAL SG 534-23	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>283419</u>	Type: <u>WELL</u>	API Number: <u>045-11921</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283420</u>	Type: <u>WELL</u>	API Number: <u>045-11923</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283421</u>	Type: <u>WELL</u>	API Number: <u>045-11922</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>283422</u>	Type: <u>WELL</u>	API Number: <u>045-11920</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296293</u>	Type: <u>WELL</u>	API Number: <u>045-15976</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296294</u>	Type: <u>WELL</u>	API Number: <u>045-15977</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296295</u>	Type: <u>WELL</u>	API Number: <u>045-15978</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296296</u>	Type: <u>WELL</u>	API Number: <u>045-15979</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>412012</u>	Type: <u>WELL</u>	API Number: <u>045-18419</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Berms	Pass	Gravel	Pass			
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT