

# Final Reclamation and Stormwater Inspection

January 27, 2017

Operator: Kerr McGee Oil & Gas- #47120

API: 001-09338

Adams County, CO

SENE Section 25 T1S R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos

Location Name: HSR-PICCADILLY #8-25

API: 05-001-09338



Google Earth aerial imagery taken October 7, 2012 of the well and tank battery location while it was active.

Inspection Photos

Location Name: HSR-PICCADILLY #8-25

API: 05-001-09338



Google Earth aerial imagery taken October 6, 2013 of the well and tank battery location approximately two months after plugging operations.

Inspection Photos

Location Name: HSR-PICCADILLY #8-25

API: 05-001-09338



Google Earth aerial imagery taken October 9, 2015 of the well and tank battery location approximately two years and two months after plugging operations. Does not appear final reclamation activities have been performed.

Inspection Photos  
Location Name: HSR-PICCADILLY #8-25  
API: 05-001-09338



**Photo 1.** Photo taken from the approximate center of the tank battery location, facing West. Does not appear final reclamation activities have been performed per Rule 1004.



**Photo 2.** Photo taken from the approximate center of the tank battery location, facing East. Equipment (i.e., riser) remains at location.

Inspection Photos  
Location Name: HSR-PICCADILLY #8-25  
API: 05-001-09338



**Photo 3.** Photo taken from the southern tank battery location, facing South. List B Colorado Noxious weed species observed at location- Scotch thistle.



**Photo 4.** Photo taken from the southern tank battery location. List B Colorado Noxious weed species observed at location- Musk thistle.