

**Inspection Photos**  
**Location Name: Wenzel 1**  
**API: 05-123-11526**



**Photo 1: Weeds around wellhead, looking NW**



**Photo 2: Weeds around tank battery, looking W**

**Inspection Photos**  
**Location Name: Wenzel 1**  
**API: 05-123-11526**



**Photo 3: Debris at E side of tank battery**



**Photo 4: Unused equipment around separator**

