

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2017

Submitted Date:

02/13/2017

Document Number:

675203828**FIELD INSPECTION FORM**
 Loc ID 334160 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener, Garrett		garrett@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	EHS
Janicek, Jake		JJanicek@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289965	WELL	PR	01/20/2011	GW	045-13933	NAUROTH 2-42D	PR
289966	WELL	PR	01/07/2011	GW	045-13932	NAUROTH 2-42C	PR
289967	WELL	PR	01/07/2011	GW	045-13931	NAUROTH 2-42B	PR
289968	WELL	PR	08/27/2009	GW	045-13930	NAUROTH 2-42A	PR
295458	WELL	PR	01/07/2011	GW	045-15764	RASBERRY 2-32C	PR
295459	WELL	PR	05/13/2015	GW	045-15765	RASBERRY 2-32D	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: CONKLIN, CURTIS

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>289965</u>	Type: <u>WELL</u>	API Number: <u>045-13933</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>289966</u>	Type: <u>WELL</u>	API Number: <u>045-13932</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>289967</u>	Type: <u>WELL</u>	API Number: <u>045-13931</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>289968</u>	Type: <u>WELL</u>	API Number: <u>045-13930</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>295458</u>	Type: <u>WELL</u>	API Number: <u>045-15764</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>295459</u>	Type: <u>WELL</u>	API Number: <u>045-15765</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT