

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

675203837**FIELD INSPECTION FORM**
 Loc ID 334529 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Bankert, Wayne	(970) 683-5419	wbankert@laramie-energy.com	Senior Regulatory & Environmental Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278342	WELL	PR	10/01/2013	GW	077-08902	MCDANIEL 2-15	PR
278343	WELL	PR	01/01/2011	GW	077-08903	MCDANIEL 2-16	PR
278344	WELL	PR	08/01/2011	GW	077-08904	MCDANIEL 2-10	PR
278346	WELL	PR	09/21/2015	GW	077-08906	MCDANIEL 2-9	PR
292512	WELL	PR	07/16/2009	GW	077-09415	MCDANIEL 2-9A	PR
292513	WELL	PR	03/17/2009	GW	077-09414	MCDANIEL 2-10C	PR
292514	WELL	PR	04/08/2015	GW	077-09413	MCDANIEL 2-10B	PR
292515	WELL	PR	09/01/2013	GW	077-09412	MCDANIEL 2-10A	PR
292516	WELL	PR	09/10/2014	GW	077-09411	MCDANIEL 2-9C	PR
292517	WELL	PR	05/06/2014	GW	077-09410	MCDANIEL 2-9B	PR
292518	WELL	PR	03/17/2009	GW	077-09409	MCDANIEL 2-15C	PR
292519	WELL	PR	12/01/2014	GW	077-09408	MCDANIEL 2-15B	PR
292520	WELL	PR	11/18/2008	GW	077-09407	MCDANIEL 2-15A	PR
292521	WELL	PR	07/16/2009	GW	077-09406	MCDANIEL 2-16C	PR
292522	WELL	PR	03/17/2009	GW	077-09405	MCDANIEL 2-16B	PR
292523	WELL	PR	01/25/2016	GW	077-09404	MCDANIEL 2-16A	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	4 Tanks stored on location. See attached photos.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	400 BBLS	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>278342</u>	Type: <u>WELL</u>	API Number: <u>077-08902</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>278343</u>	Type: <u>WELL</u>	API Number: <u>077-08903</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>278344</u>	Type: <u>WELL</u>	API Number: <u>077-08904</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>278346</u>	Type: <u>WELL</u>	API Number: <u>077-08906</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292512</u>	Type: <u>WELL</u>	API Number: <u>077-09415</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292513</u>	Type: <u>WELL</u>	API Number: <u>077-09414</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292514</u>	Type: <u>WELL</u>	API Number: <u>077-09413</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292515</u>	Type: <u>WELL</u>	API Number: <u>077-09412</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292516</u>	Type: <u>WELL</u>	API Number: <u>077-09411</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292517</u>	Type: <u>WELL</u>	API Number: <u>077-09410</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292518</u>	Type: <u>WELL</u>	API Number: <u>077-09409</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292519</u>	Type: <u>WELL</u>	API Number: <u>077-09408</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292520</u>	Type: <u>WELL</u>	API Number: <u>077-09407</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292521</u>	Type: <u>WELL</u>	API Number: <u>077-09406</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292522</u>	Type: <u>WELL</u>	API Number: <u>077-09405</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>292523</u>	Type: <u>WELL</u>	API Number: <u>077-09404</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Could not do complete stormwater inspection due to snow cover.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203838	Mc Daniels 2-9	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075513