

Inspection Photos
Operator: St. Croix Operating #81490
Location ID: 448370



Figure 1: Photo taken from the southwest corner of the location, facing north. Photo shows silt fence used as a stormwater and sediment control BMP has been installed prior to construction/surface disturbing activities.



Figure 2: Photo taken from the southwest corner of the location, facing north. Photo shows silt fence used as a stormwater and sediment control BMP has been installed prior to construction/surface disturbing activities.