

Reclamation Inspection

02/13/2017

Operator: Vista Operating Inc #100128

Location ID: 317408

Inspection Doc. Number: 682501652

Washington County, CO

SWNE Section 33 T2S R49W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Vista Operating #100128
Location ID: 317408



Photo 1: Photo taken from the north end of the location, facing south. Photo shows location remains predominantly bare and exposed soil, with very little desirable perennial vegetative cover. Location appears to be experiencing wind erosion.



Photo 2: Photo taken from the east end of the location, facing west. Photo shows location remains predominantly bare and exposed soil, with very little desirable perennial vegetative cover. Location appears to be experiencing wind erosion.

Inspection Photos
Operator: Vista Operating #100128
Location ID: 317408



Photo 3: Photo taken from the reference area, with a similar slope and soil type, west of the location. Photo shows vegetation on the reference area.

Inspection Photos
Operator: Vista Operating #100128
Location ID: 317408



Photo 4: Photo taken north end of the location at the access road. Photo shows metal stake on the west side of the access road.



Photo 5: Photo taken north end of the location at the access road. Photo shows metal stake on the east side of the access road.

Inspection Photos
Operator: Vista Operating #100128
Location ID: 317408



Photo 6: Photo taken from the north end of the location, facing east. Photo shows access road has not been adequately reclaimed.

Inspection Photos
Operator: Vista Operating #100128
Location ID: 317408



Photo 7: Photo taken access road northeast of the location at coordinates 39.83686/-102.85993. Photo shows pipe riser that has not been removed.